

1962

Volkswagen Beetle Type 113

Engine	1200 cc H4
Transmission	4 Speed Manual
Interior	Red Vinyl
Mileage	68,000 (Actual)
Vin #	4686889
Stock #	0000019

Drivetrain

Engine Type	Gasoline
Engine Size	1200 cc H4
Fuel Specification	91 Octane or below
Fuel Delivery System Type	1 Barrel
Transmission Type	4 Speed Manual

Chassis

Exhaust Type	Single Exhaust
Muffler Type	Factory Replacement

Body

Body style	Sedan
Doors	2
Paint code	L456
Body color original	No
Stripes	No



No single car model, with the exception of the Ford's Model T, has played such a major role in the changing of automotive history, as the Volkswagen Beetle, also know as the "Bug". More than any other make, this German built Volkswagen paved the way for the import invasion of the 1950's to the 1960's, which has affected the types of cars turned out by Detroit for years and until this day. Without question the "people's car", which is the direct translation of Volkswagen, had the same impact in Germany and throughout Europe as it did when it arrived on America's Shores. Late in 1930 the formation of a new company, Dr.-ing.h.c Ferdinand Porsche Gmbh, which employed air cooled engine expert, Joseph Kales, saw the creation of small cars a challenge. Early on this is evident in one of the firm's first projects, known as Project 12, which eventually evolved into this amazingly iconic vehicle, the Beetle. Volkswagen's desire to continuously improve was also evident in the progress of their air cooled engines, which started out early on as a 1200cc engine and gradually progressed to a 1600cc engine. In addition to its impressive history the condition of this particular Volkswagen you are viewing is also very impressive. A complete, total and high quality professional restoration has been done to this vehicle. It has been meticulously maintained and stored for may years in a heated

space by a avid classic car enthusiast and collector. Every component and part works and the entire vehicle above and underneath and from bumper to bumper is clean and free of any corrosion. Detailed Vehicle Condition Engine: Runs and drives superbly, has plenty of horsepower that is constant throughout acceleration and has not major oil and fluid leakage evident. Transmission/ Clutch: 4 speed Volkswagen manual transmission that shifts with ease and readiness. There is no major oil or fluid leakage evident. Drivetrain/ Axels: Stock equipment that is in excellent working condition and that operates as intended. Axels, Axel boots and rear drive system are in perfect condition and there is no major oil or fluid leakage evident. ...

Classic Cars of Boston

7 Beacham St Everett, MA 02149
